Oil Field Environmental Incident Summary

Responsible Party: CALIBER MIDSTREAM NORTH DAKOTA LLC **Well Operator:** CALIBER MIDSTREAM NORTH DAKOTA LLC

Well Name: MOEN 1-35 SWD

Field Name: TIMBER CREEK Well File #: 9388

Date Incident:3/11/2016Time Incident:03:00Facility ID Number:County:MCKENZIETwp:150Rng:100Sec:35Qtr:

Location Description:

Submitted By: Skip Vest Received By:

Contact Person: Skip Vest

1200 17TH ST SUITE 2100 DENVER, CO 80202

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building: 0.4 Mile

Distance Nearest Water Well:

Type of Incident: Other

Release Contained in Dike: Yes - On Constructed Well Site Reported to NRC: No

Spilled Units Recovered Units Followup Units

Oil

Brine 190 Barrels 185 Barrels 185 barrels

Other

Description of Other Released Contaminant:

Inspected: Written Report Received: 5/4/2016 Clean Up Concluded: 3/13/2016

Risk Evaluation:

No immediate risk, the majority of produced water was contained within secondary containment and returned to tanks via hydrovac.

Areal Extent:

Potential Environmental Impacts:

Impacts to pad soils only. No possibility of impacts to surface or groundwater.

Action Taken or Planned:

Liquids were hydrovacced and returned to tanks. Pad soils will be treated with an NDIC approved insitu treatment.

Wastes Disposal Location:

Agencies Involved:

Updates

Date: 3/14/2016 Status: Reviewed - Assigned to Other Agency Author: O'Gorman, Brian

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

According to the report, the release remained on the constructed well site. NDIC retains oversight.